



City of Longmont
Survey Benchmark list
Updated: AUGUST 2017

City of Longmont Benchmarks (updated 8/2017)

BENCHMARK	LOCATION	NAVD_1988	NGVD_1929	CITY MAINTAINED	LAST_RECOVERY_DATE	LAST_RECOVERY_CONDITION
001	N.W. corner of 4th & Kimbark at North side of City of Longmont Development Services Center bldg. on West end of bottem step (USGSJR61)	4981.14	4977.99	Y	<null>	<null>
004	N.E. corner of 9th & Collyer at back of walk at east P.C., 2.5' W. of signal pole.	4989.84	4986.69	Y	<null>	<null>
005*	(DESTROYED/MISSING) N.W. corner of 11th & Main at back of walk at M.P.O.C.	4997.72	4994.57	Y	1/2015	MARK NOT FOUND
008	S.W. corner of 15th & Bross at back of walk at west P.C.	5027.69	5024.54	Y	<null>	<null>
009	S.E. corner of 15th & Bowen at back of walk at east P.C.	5028.66	5025.51	Y	<null>	<null>
010	N.E. corner of Mt. View & Lincoln at back of walk at east P.C.	5014.44	5011.29	Y	<null>	<null>
011	N.W. corner of 12th & Grant in sidewalk at north P.C.	5005.52	5002.37	Y	<null>	<null>
015	S.W. corner of 9th & Sumner at back of walk at 6' of south P.C.	5033.55	5030.4	Y	<null>	<null>
017	(DESTROYED/MISSING) S.W. corner of Sunset & Sunset Circle, N. entrance, at back of walk at south P.C.	5067.62	5064.47	Y	1/2015	MARK NOT FOUND
018	S.W. corner of Longs Peak at Sunset at back of curb at south P.C.	5077.94	5074.79	Y	5/2016	GOOD
020	N.E. corner of 3rd & Sunset at back of walk at 19' north of Fl of 3rd ave.	5051.65	5048.5	Y	<null>	<null>
021	N.E. corner at 3rd & Vivian at back of curb, at CB	5036.3	5033.15	Y	<null>	<null>
024	N.W. corner of 3rd & Bowen at back of curb, 3' west of C.B.	5028.62	5025.47	Y	<null>	<null>
026	N.E. corner of 4th & Pratt at back of curb, 3'N.of N. edge of walk.	5002.57	4999.42	Y	<null>	<null>
028	N.E. corner of 3rd & Grant at north P.C. in top of curb	5034.38	5031.23	Y	<null>	<null>
029	S.E. corner of 9th and Martin at 1' back of curb at east P.C.- WAS REPLACED AFTER 2013 - ELEVATION UNCONFIRMED	<null>	<null>	Y	<null>	RECENTLY REPLACED NO ELEV.
030*	S.W. corner of 9th & Main on top of curb at C.B.	4995.25	4992.1	Y	8/2014	GOOD
037	N.E. corner of Mt. View & Gay at back of walk at north P.C.	5017.74	5014.59	Y	<null>	<null>

BENCHMARK	LOCATION	NAVD_1988	NGVD_1929	CITY MAINTAINED	LAST_RECOVERY_DATE	LAST_RECOVERY_CONDITION
038	N.E. corner of 11th & Aspen at back of walk at east P.C.	5003.06	4999.91	Y	<null>	<null>
043	S.W. corner of Lashley and Marshall pl. at back of walk at 8' W. of stop sign at west P.C.	4978.09	4974.94	Y	<null>	<null>
046*	N.W. corner of Lashley & Reed at back of walk at north P.C.	4973.68	4970.53	Y	<null>	<null>
050	S.E. corner of 19th & Collyer at back of walk 2.5' south of south P.C.	5022.97	5019.82	Y	<null>	<null>
052	S.E. corner of 3rd & Arapahoe at 4' south of south FL and 3' west of west P.C.	5022.92	5019.77	Y	<null>	<null>
053	N.W. of Clover Basin dr. & Grandview Meadows dr. on S. corner irrigation structure @ 15.4' N.W. of FH & 17.3 W. of W. FL of Grandview Meadows dr.	5045.07	5041.92	Y	<null>	<null>
054	Brass cap in E. corner of irrigation structure @ +/- 45' W. of Sandstone Ranch visitors center & 55' S. of two bay garage	4899.65	4896.5	Y	5/2017	GOOD
057*	N.W. cor. 1st. & Main on E. steps of old City power plant bldg. North of R.R. tracks (NGS PT JR-60)	4951.76	4948.61	Y	6/2016	GOOD
060	N.E. corner of S. Pratt Parkway & Delaware at back of curb in sidewalk at east P.C.	4951.9	4948.75	Y	<null>	<null>
061	N.E. corner of Pratt & Jersey at back of walk at north P.C.	4964.75	4961.6	Y	<null>	<null>
062	West side of Main St @ Jersey Ave - at east end of median back of curb	4957.18	4954.03	Y	8/2012	GOOD
064	S.E. corner of Mt. View & Fordham at back of walk at east P.C.	5078.81	5075.66	Y	<null>	<null>
068	N.E. corner of 17th & Centennial at back of walk at north P.C.	5020.02	5016.87	Y	<null>	<null>
074	N.W. corner of 11th & Frontier at back of walk at west P.C.	5037.54	5034.39	Y	<null>	<null>
077	S.W. corner of James & Grand at 12' NW of fire hydrant at back of walk	4959.61	4956.46	Y	<null>	<null>
078	N.W. corner of Bowen & Iowa at 14' south of fire hydrant at back of pan at W. P.C.	4969.46	4966.31	Y	<null>	<null>
079	S.E. corner of Longs Peak & Bowen at back of curb at south P.C.	5003.59	5000.44	Y	<null>	<null>
083	S.W. corner of 16th & Spencer at back of walk at west P.C.	5051.08	5047.93	Y	<null>	<null>
085	N.W. corner of Northwestern & Harvard at back of walk	5088.67	5085.52	Y	<null>	<null>

BENCHMARK	LOCATION	NAVD_1988	NGVD_1929	CITY MAINTAINED	LAST_RECOVERY_DATE	LAST_RECOVERY_CONDITION
	at 5' west of P.C. and 18' west of hydrant					
086	N.W. corner of Mt. View & Purdue at back of walk at west P.C. -cut arrow points toward location of brass cap - MARK IS LEANING - NEEDS ELEV CHECK - NEEDS REHAB?	5069.57	5066.42	Y	6/2017	POOR
088	NW Corner of 15th Ave and Twin Sisters Dr - back of walk at North PC (RECENTLY RE-DISCOVERED - Elevation Not Checked)	<null>	<null>	Y	7/2015	<null>
089	15th & Lamplighter in range box at intersection of centerlines	5016.85	5013.7	Y	<null>	<null>
093	N.W. corner of 1st & Bowen at back of walk at north P.C. at 4' south of 2' walk	4962.46	4959.31	Y	5/2013	GOOD
094	N.E. corner of 1st & Sherman Court at back of walk at east P.C.	4966.18	4963.03	Y	<null>	<null>
096*	S.W. corner of Gay & Hwy 66 at +/- 67' south of center line of Hwy 66 and 1.1' west of back of walk and +/- 8' south of fire hydrant	5050.18	5047.03	Y	<null>	<null>
101*	S.E. corner of Hover & Hwy 66, cut square on S.E. end of concrete irrigation headwall	5096.85	5093.7	Y	<null>	<null>
108	(DESTROYED/MISSING) S.W. corner of Pike & Main @ W. P.C. in S.W. corner 6' type R inlet in C.L. 8' bike path 4' W. of M.H.	4979.12	4975.97	Y	1/2015	MARK NOT FOUND
109	Rough & Ready Ditch & RR tracks N. of 21st. Ave.on east side of tracks @ 0.5' N. of north headwall. Of ditch	5052.72	5049.57	Y	<null>	<null>
110	45' south of water tank of Skyline High School (See book 199 p.79 for reference marks)	5086.56	5083.41	Y	<null>	<null>
113	Piece of R.R. track buried on end with "X" on top at NW corner or Railroad and HWY 66 - 4' North and 2' East of fence corner - 33.5' West of CL of R.R. Tracks	5065.18	5062.03	Y	<null>	REPORTED MISSING / NOT CONFIRMED
117*	Top of bolt w/cut square on irrigation structure at W. Side at Rough & Ready Ditch, 185' S. of Mtn. View, 21.5' E. of fence, and +/- 500' W. of Pace	5044.8	5041.65	Y	<null>	<null>
118*	#5 rebar glued in concrete headwall at N.E. corner of bridge @ 21st & Oligarchy @ Main st.	5032.77	5029.62	Y	1/2015	GOOD
120*	S.W. corner Mt View & Main st. in N.E. corner type "R" inlet	5004.74	5001.59	Y	<null>	<null>
122*	In south end of west headwall Oligarchy ditch @ Hover Rd	5074.78	5071.63	Y	<null>	<null>
123*	N.W. corner 17th. ave. & Hover st. in S.E. corner signal pole base (RESET SOMETIME AFTER 2007 TO	5072.5	5069.35	Y	<null>	<null>

BENCHMARK	LOCATION	NAVD_1988	NGVD_1929	CITY MAINTAINED	LAST_RECOVERY_DATE	LAST_RECOVERY_CONDITION
	CURRENT DESCRIPTION)					
125*	In outlet structure at detention pond at N.W. corner of 9th & Hover +/-80' N. of CL 9th +/-0.1 mile W. of Hover	5032.92	5029.77	Y	<null>	<null>
126*	#5 rebar glued in N.W. corner of concrete C.B. at 100' E. of the E. FL of Hover and .35 mile N. of Nelson Rd.	4976.63	4973.48	Y	<null>	<null>
127*	N.W. corner of area inlet 12.5' N. of N. FL of 17th & 715' E. of CL of Harvard St.- N of CB	5083.98	5080.83	Y	5/2017	GOOD
128	7.0'N. of N. FL of 17th and 166'W. of CL of Denver Way	5104.75	5101.6	Y	7/2017	MARK NOT FOUND
130*	N.W. corner of Hwy 119 & Pace, in lower and westerly headwall of Oligarchy Ditch +/-105' W. of CL of Pace (lower cap) R.O.W. marker	4989.49	4986.34	?	<null>	<null>
131	N.E. corner Nelson and Hover in SW corner of irrigation structure.	4991.95	4988.8	Y	1/2015	GOOD
133	S.E. corner of Boston & St. Vrain River in walk on bridge	4968.89	4965.74	Y	5/2017	GOOD
134	S.E. corner of C.B. at N.E. corner of Mtn. View and Hover	5047.27	5044.12	Y	<null>	<null>
135	Airport rd. and Dry Creek bridge in S.W. wingwall at 5' W. of W. headwall	5017.36	5014.21	Y	<null>	<null>
136	West side Weld County Rd#1 +/- 370' N .of 17th ave - chiseled square on S.E. side of transmission pole base (Pole #102)	4989.54	4986.39	N	11/2012	GOOD
138	SW Corner Sunshine Ave & Weld County Rd #1 - Also 0.3 miles S. of 17th Ave - cut "+" in E. Bolt of transmission pole #105 on West side road	4988.6	4985.45	N	<null>	<null>
139	South end of Union Res. On West side boat ramp brass cap #28	4959.02	4955.87	Y	8/2017	GOOD
140	West side Weld County Road #1 at 20' North of East 1/4 corner Sec. 25, T.3N., R.69W cut "+" on E. Bolt transmission pole #98	4997.37	4994.22	N	<null>	<null>
141	21st Ave. and Oligarchy bridge #5 rebar in West end of N. headwall @ N. Side Garden Acres Park	5048.33	5045.18	Y	1/2015	GOOD
142	SE. corner 21st ave. & Hover 49' S. of S. FL of 21st.ave. in top of curb on type R CB	5067.86	5064.71	Y	1/2015	GOOD
143	N.E. corner 17th and Airport at back of walk at MPOC.	5073.2	<null>	Y	7/2017	MARK NOT FOUND
144	Intersection of 21st and Gay Street #5 rebar on the N.E. corner of Oligarchy bridge in high part of wingwall	5034.17	5031.02	Y	5/2016	GOOD
145	Intersection of 21st and Francis in top center of E. headwall of Oligarchy bridge	5042.37	5039.22	Y	<null>	<null>

BENCHMARK	LOCATION	NAVD_1988	NGVD_1929	CITY MAINTAINED	LAST_RECOVERY_DATE	LAST_RECOVERY_CONDITION
146	S.E. corner of Airport Rd. and Nelson Rd. #5 rebar in top S. end irrigation structure (buried in landscaping) reference mark 4.8' N of BM (elev. = 5024.31)	5024.39	5021.24	<null>	<null>	<null>
147	SW corner of Mt View Ave.& Airport Rd.@ Top of NE bolt on signal pole base	5038.28	5035.13	Y	7/2017	GOOD
148	St Vrain bridge & Airport Rd. in CL walk @ SE corner of bridge	5029.26	5026.11	Y	7/2016	GOOD
149	SW corner of St Vrain Rd. & Airport Rd.@ +/-108' S. of S. FL of St Vrain Rd. in top E. side of irr. structure	5026.82	5023.67	Y	7/2012	GOOD
150	S. side Nelson Rd +/- 60' W. of the C.L. Schlagel St. in N.W. corner of type R inlet (This mark was reset after 2008-the previous elevations = [88VD=5015.38][29VD=5012.23])	5015.96	<null>	Y	7/2017	GOOD
151	SE corner Nelson and Fordham - #5 Rebar in NW side of base of Transmission pole #14 (POLE/BASE WERE REPLACED AROUND 2010 SEE BM 190)	5004.85	5001.7	N	7/2017	MARK NOT FOUND
152	W. side Weld County Rd #1 at intersection of road #28, cut square in E. Side base of transmission pole #100	4987.49	4984.34	N	<null>	<null>
153	W. Side Weld County Rd. #1 at 150' south of RR tracks and 85' west of CL Weld County Road #1, cut square in S.E. end of S.E. wingwall of Oligarchy Ditch irrigation structure (MARK NOT FOUND)	4975.91	4972.76	Y	8/2017	MARK NOT FOUND
156	Hwy 119 bridge over RR tracks on east end of north headwall. CDH cap	5024.72	5021.57	N	1/2015	GOOD
157	+/- 77'N of CL Hwy 66 & +/- 69'E of CL of N. 75th & 2' W of P.P. (POOR CONDITION - LOOSE CONCRETE)	5164.76	5161.61	Y	6/2016	POOR
158	USGS BM 5100 , 25'S. of CL 17th Ave. & 30' E. of CL of N. 75th @ S.E. corner of intersection, in the town of Hygiene. In water valve box. (ELEVATION QUESTIONABLE DUE TO CONDITION OF MARK)	5100.21	5097.06	N	5/2017	POOR
159	42' S. of CL St. Vrain Rd. & 73' E. of CL of N. 75th @ 1.5' N. of fence.	5080.46	5077.31	Y	1/2015	GOOD
161*	Dedication cap E side Hover Rd Bridge @ Lefthand Creek - on top center of East headwall - west side of bike path - 62' south of Boulder County Cap	4997.18	<null>	Y	<null>	<null>
162	36' W. of CL of Disk drive & 80' N. of CL of Nelson Rd. In headwall of outlet for pond.	5065.2	5062.05	Y	<null>	<null>
163	30' S. of CL of Nelson Rd. & 200' W. of W. access to Amgen (4000 Nelson Rd) & 0.25 mile W. of Airport Rd. In N. side of headwall of Peck ditch structure.	5042.23	5039.08	Y	5/2017	GOOD

BENCHMARK	LOCATION	NAVD_1988	NGVD_1929	CITY MAINTAINED	LAST_RECOVERY_DATE	LAST_RECOVERY_CONDITION
164	33' E. of CL Airport & 100' S. of Pike Rd. & 1.5' E. of E. FL on Airport Rd. between walk and curb	5054.15	5051	Y	<null>	<null>
166	N. side Hwy 66 @ 1.25' S. of fence @ 95'N of CL of Hwy 66 & 600" W. of CL of County Line Rd #1	5011.47	5008.32	Y	<null>	<null>
167	N.E. corner of 17th. & Pace @ 9 ft. S. of N. P.C. between 8ft. walk & cobblestone.	5016.38	5013.23	Y	1/2015	GOOD
169	E. side Alpine st. & oligarchy ditch on top curb @ CL C.B.	5007.8	5004.65	Y	1/2015	GOOD
170	# 4 rebar W. side Hover rd. & James ditch in S.E. end headwall 15' W. of the W. FL Hover rd. & 72' N. of the N. edge of R.R. track along back of walk	5019.8	5016.65	Y	<null>	<null>
173	South corner headwall of drainage structure at the NW corner of N 105th St and Plateau Rd	4973.19	4970.04	Y	1/2015	GOOD
174	N. side 17 th. Ave W. of Ute Creek dr. @ Spring gulch bridge on nwc of headwall	4997.33	4994.18	Y	<null>	<null>
175	N. side Clover Basin dr. @ 42' W. of Dry creek #1 bridge & 295' E. of CL of N.75th. in back center 10' type R inlet	5067.81	5064.66	Y	1/2015	GOOD
176	Ken Pratt blvd. bypass & Lefthand creek bridge on top of West retaining wall.	4945.93	4942.78	Y	1/2015	GOOD
177	Ken Pratt blvd. bypass & St Vrain river bridge on top of East retaining wall	4935.74	4932.59	Y	1/2015	GOOD
178	NW. corner of Hwy. 119 & county line rd. in top of SE. bolt of signal pole base.	4972.31	4969.16	Y	<null>	<null>
179	SE corner Hwy. 119 & Zlaten Dr. @ 100' S. of CL of Hwy.119 & 75' E of CL of Zlaten Dr. cap in SE. corner of irr. Structure.	4940.86	4937.71	Y	5/2017	GOOD
180	Martin st. @ 450' S. of 1st. Ave & 55' E. of Martin st. in CL. of & N. end of concrete sanitary sewer vault.	4938.65	4935.5	Y	5/2015	GOOD
181	SW. corner of Hwy. 119 & E. sandstone ranch entrance (Sandstone Dr.) @ +/-300' S. of CL Hwy. 119 & +/- 130' W. of CL Sandstone Dr. cap in top E. headwall of drainage structure.	4927.01	4923.86	Y	5/2017	GOOD
182	E. side Francis st. @ +/- 295' n. of the C/L of 12th. ave. @ back of walk.	5007.77	5004.62	Y	<null>	<null>
183	N.W. quadrant of intersection of Pike rd. & Renaissance dr. @ E. edge of 8' walk 1'N. of N. edge of handicap ramp.	5054.46	5051.31	Y	1/2015	GOOD
184	NE. corner 17th & Alpine on top E. corner head wall of outlet structure @ SE corner detention pond.	5047.6	<null>	Y	<null>	<null>

BENCHMARK	LOCATION	NAVD_1988	NGVD_1929	CITY MAINTAINED	LAST_RECOVERY_DATE	LAST_RECOVERY_CONDITION
185	W. side Deerwood dr. +/- 330' N. of the C.L Mt.View @ back of walk on S.E. corner of 6' type R inlet.	4992.22	4989.07	Y	1/2015	GOOD
186	W. of Pace (+/- 1/2 mi.) on SSW portion transmission pole base @ "T" intersection of 8' bike paths Pole # 4	5033.25	5030.13	N	1/2015	GOOD
187*	W side Pace st.1/2 mi. S. of Ute hwy 66 on top center W. head wall Spring Gulch bridge, +/- 71' NNE of CL transmission pole #8	5018.85	<null>	Y	1/2015	GOOD
188	Cut "+" on top of bolt in Southerly bolt group on Transmission pole # 12, 4th pole E. of Pace st (+/- 1/2 mi. E. of Pace st. & 1/2 mi. S. of Ute hwy. 66).	5027.86	<null>	N	<null>	<null>
189	(OLD DESCRIPTION) Cut "+" @ N.E. corner of Fordham & Clover Basin dr. on top of S. bolt of transmission pole base (pole # 19) (POLE WAS REPLACED AFTER 2010)	5007.15	5004	N	<null>	MARK NOT FOUND
189R	Se. corner Fordham St. & Clover Basin Dr.,in NE. corner 5' type "R" inlet 5' S. of S. pc near, NW of NW corner sub station wall.	5007.44	<null>	Y	1/2015	GOOD
190	SE Cor Fordham & Nelson - Cut x in top of N. Bolt of NWly bolt pair for Transmission pole #15 (Previous vicinity of BM 151)	5006.32	<null>	N	<null>	<null>
191	S. side Horizon Parkway @ intresection of Harvard St. in top of N. head wall of bridge, over Longmont supply Ditch.	5092.73	<null>	Y	7/2013	GOOD
192	N. side Pike Rd. @ Lefthand Creek, in top center N. head wall of bridge	4974.92	<null>	Y	1/2015	GOOD
193	Cut square - West side S. Sunset Street at Lefthand Creek bridgein top center of west head wall	4980.65	<null>	Y	<null>	<null>
194	W. side N.95th Cut square on S.W corner headwall of bridge @ Rough and Ready ditch +/- 1.5 mi. N. of Ute Hwy. 66	5101.68	<null>	Y	<null>	<null>
195	E. side W.C.L. rd.# 1 & 9th Ave., In N. end of.W. wall irr. stru.. 2.0 S. of wingall junction 17.0 N.W. of dedication cap (ded. cap @ 1.0 W. of gate hoist)	4969.43	<null>	Y	5/2017	GOOD
201*	N.E. corner of Pace & Winslow Cr. At back of walk at N. PC	5054.89	5051.74	Y	1/2015	GOOD
202	N.W. corner of Martin & Pike at 34' west of FL, 8' south of PP	4954.45	4951.3	Y	8/2013	GOOD
301	E. side of Sunset at Burlington Cemetery, 13' north of gate at back of walk	5013.36	5010.21	Y	<null>	<null>
302	S.E. corner of Boston & Sunset 61'E. of CL of Sunset	4966.05	4962.9	Y	<null>	<null>

BENCHMARK	LOCATION	NAVD_1988	NGVD_1929	CITY MAINTAINED	LAST_RECOVERY_DATE	LAST_RECOVERY_CONDITION
	and 50.5' S.E. of PP and 67.5' S of CL of Boston on top of irrigation ditch wall @ MPOC on W. side.					
312	N. side of Rogers Rd. at +/-0.45 mile E. of Airport Rd. cut square in concrete irrigation box at east side ditch at gate at +/-50' N. of Rogers Rd.	5014.05	5010.9	Y	<null>	<null>
400	@ 525' E. of the intersection of 9th & the R.R. tracks and 125'N. of 9th , on the N corner of a CB in Twin Peaks Golf Course	5012.42	5009.27	Y	6/2016	GOOD
401*	West side of Hover St. @ St. Vrain River at end of S.W. wingwall on bridge - cut "+" (A CITY CAP IS UNDER THE RAILING - ELEVATION LISTED IS TO CONCRETE NEXT TO CAP)	4991.17	4988.02	Y	3/2015	GOOD
402*	(DESTROYED/MISSING) S.E. corner of Hover & Dry Creek at S.E. corner of concrete box on headwall at Twin Peaks Mall (CONCRETE BOX REPLACED 2016)	4990.97	4987.82	Y	11/2016	MARK NOT FOUND
408	N. side Mt. View & Oligarchy ditch @ back of walk	5012.81	5009.66	Y	1/2015	GOOD
410	Hwy 119 at Twin Peaks Mall entrance at top of curb at S. end of island	4994.79	4991.64	Y	<null>	<null>
412	(DESTROYED/MISSING) N.W. corner of Bowen & Ken Pratt Blvd. at top of curb at M.P.O.C.	4964.54	4961.39	Y	1/2015	MARK NOT FOUND
A411	N. side Hwy 66, W. of Hwy 36, in cliff face 5' above ground 41.1' N.W. of cap in Westerly half of the N. headwall of bridge over "supply ditch"	5309.27	5306.12	N	3/2014	GOOD
CDH 1*	(DESTROYED/MISSING) Main & St. Vrain River at W. Side of street @ N. end of bridge , in walk. (BRIDGE REPLACED IN 2016)	4953.7	4950.55	N	1/2017	MARK NOT FOUND
CDH 2*	N.W. corner of Oligarchy Ditch & Hwy 119 on N. headwall +/-75' W. of CL of Pace (upper cap)	4992.78	4989.63	N	<null>	<null>
CDH 3*	S.E. corner of Main & Hwy 66 at S. end of headwall of Rough & Ready ditch box.	5069.57	5066.42	N	<null>	<null>
F-030*	N. side of Hwy 66 at N. ¼ corner of Section 28 at fence corner.1/2 mile east of hover rd. 50' W. of the S.W. corner house, +/- 6' E. of P.P.	5063.93	5060.78	N	<null>	<null>
G1*	N.E. corner of Ute Hwy 66 and Pace st.(N.119th), 32.8'S of fence, 25'E. of CL of field entrance Rd, 73'N. of CL of Ute Hwy, and 58.5' E. of PP	5037.97	5034.82	Y	<null>	<null>
G3*	Ute Hwy (66) 48.5 W. of CL of N. 87th (Airport Rd), 108'N of CL of Ute Hwy, 25.3' N.W. of PP, 58' N. of N. end of 30" culvert, 10.8' S.E. of fence	5123.08	5119.93	Y	<null>	<null>
G5*	S.E. corner of 9th & Bowen St., 21.4' N.W. of corner of	4998.89	4995.74	Y	<null>	<null>

BENCHMARK	LOCATION	NAVD_1988	NGVD_1929	CITY MAINTAINED	LAST_RECOVERY_DATE	LAST_RECOVERY_CONDITION
	house, 72.7' S. of N. FL of 9th Ave. and 75.5' E. of FH @ +/- 0.8 back of walk.					
G6*	S.E. corner of 9th & Pace, 36'E. of CL of Pace, 100' S. of CL of 9th Ave. and 8' W. of fence	5066.04	5062.89	Y	<null>	<null>
G8*	S. Bowen @ Service Center, 14.8' W. of W. FL of Bowen St., 33.5' N. of the N. edge of drive @ S. entrance 65' S. of CL of S. Gay St. +/- 0.40 below ground.	4975.79	4972.64	Y	<null>	<null>
G9*	Quail Rd. & Airport, 21.8' S. of CL of Quail Rd., 10.5' S.W. of Asphalt Drive, 112.5' S. of S.W. corner of brick house, and 8' S.E. of S. end of 15' CMP running under Quail Rd.	5027.29	5024.14	Y	<null>	<null>
H454	E. side N. 87th / (Airport rd) @ Lefthand creek bridge N. of Hwy. 119 in sidewalk 8' E. of F.L.	5029.49	5026.34	N	<null>	<null>
J320	Longmont Airport at +/-724' N.W. of CL of taxiway at S. end and 155' N.E. of CL of runway in range box	5030.89	5027.74	N	<null>	<null>
LH2*	Main St E. side & Lefthand Creek at N. end of E. headwall	4957.93	4954.78	N	<null>	<null>
M454	@ base of transmission pole on S side of Price Rd @ RR tracks. N of Nelson Rd.	4970.2	4967.05	N	<null>	<null>
N454	@ base of transmission pole on S side of Price Rd. @ 125' W of Boston Ave.	4958.36	4955.21	N	<null>	<null>
T410*	0.6 miles W. on Hwy 66 from junction of Hwy 287, 196'E of the S.E. corner of a metal building, 180' E. of the center of a private drive, 97' N. of the CL of the Hwy, 2' W. of a u	5049.7	5046.55	N	<null>	<null>
U410*	1.45 miles W. of Hwy 287 on Hwy 66, 565' E. of the CL of N. 95th,(Hover rd.) 93.2' N. of the CL of Hwy 66, and 5.6' E. of a utility pole. (rod in range box)	5090.1	5086.95	N	<null>	<null>
V410*	2.05 miles W. of Hwy 287 on Hwy 66, 103' N. of the CL of Hwy 66, 85' W. of the center of Anahawa St. and 4' W. of a utility pole at a utility line crossing . (rod in range box)	5109.02	5105.87	N	<null>	<null>
W410*	2.8 miles W. of Hwy 287 on Hwy 66, 0.25 miles W. of 87th St.,(Airport rd.) 100' N. of the CL of Hwy 66, 67.6' E. of a utility pole, 62'N. of the N. end of a concrete culvert, and	5115.36	5112.21	N	<null>	<null>
X410	½ mile E. of N. 75th & 97' N. of CL of Hwy 66 & 1' S. of fence & 5.2' W. of PP. (rod in range box)	5148.22	5145.07	N	<null>	<null>